

United Kingdom - Preston Routine Repair

EasiCollar 15"

Repair & Branch Solutions

Project

EasiCollar used to repair a 15 inch cast iron pipe with a leaking run lead joint.

Client

United Utilities

Contractor

Enterprise