

East Borneo - Samarinda

Leaking Pipework - Water Treatment Works

Next Generation UltraGrip



Project

Problem - A 400 mm PE100 SDR 17 was leaking because customer had initially selected low grade compression fittings which were not able to grip the pipe. This pipe was taking raw water and transporting it to a local water treatment plant.

Solution - UltraGrip was installed to ensure a trouble free solution for a pipe that was leaking badly.

Client

PDAM Samarinda

Distributor

PT Duta Prima Utama - Jakarta

Crane BS&U are solely the provider of products and have no direct influence on, or take any responsibility for any working practices employed or depicted in the images enclosed to install such products.